

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,874,134 B1
APPLICATION NO. : 09/731535
DATED : March 29, 2005
INVENTOR(S) : Collin et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 5, line 20, "generic HOL" should be --generic HDL--.

Column 8, line 47, "the state 0001is" should be --the state 0001 is--.

Column 10, line 67, "clock 15, signal" should be --clock 15 signal--.

Column 16, line 19, "EUR 0X" should be --EUR0X--.

Column 20, line 22, "for the generic HDL," should be --for the generic HDL--.

Column 22, line 21, "function Fd 0." should be --function Fd=0--.

Signed and Sealed this

Twenty-fourth Day of July, 2007



JON W. DUDAS
Director of the United States Patent and Trademark Office